

**CS-800 (Carbon & Sulfur Analyzer Consumables)**

Required consumables		
90200		Anhydrone (magnesium perchlorate), 454 g
90210		Sodium hydroxide, 500 g
90290		Copper oxide, 100 g (required for analyzers with 1xC or 2xC)
90235		Filling for halogen trap
88400-0122		Filling for carrier gas purification furnace
Optional consumables		
90149		Ceramic crucibles, premium, Ø 1", foil-wrapped, 1,000 pieces
90220		Tungsten, 2,500 g
90331		Glass wool, 454 g
90340		Cellulose, 100 g
90341		Cellulose, 50 g
90330		Quartz wool, 50 g
90260		Pure iron accelerator, 908 g
92400-3010		Steel, chips, 100 g, <0.001% C
92610		Tube of high vacuum grease
Spare and Wear Parts		
11105		Metal dust filter
11180		Dust filter cartridge
11185		Paper filters, 10 pieces
13067		Combustion coil
14045		Cleaning brush for combustion tube
14130		Combustion tube
77210		Oscillator tube
11062		Reagent tubes 160x16 mm, 2 pieces
11064		Reagent tubes 280x16 mm, 2 pieces
14072		Ceramic heat shield for brush
14168		Pedestal
20040		Catalyst tube
70030		O-rings for CS-800, 1 set
77032		Circuit breaker 20A
71036		Cleaning brush for metal dust filter
71031		Metal brush
71010		Brush